



**IMPORTADORA
ISIS**

**Importación, Exportación
y Comercialización de Repuestos
de Vehículos**
Ignacio Carrera Pinto #1161, Rancagua.
Fono: 72-2-583570
ventas@importadoraisis.cl



ZEN 0141



D:9
L:62
P:29,64
E:10
IP:13
C:46,5
CW

HITACHI:ISUZU KB20/
NISSAN SUNNY/120Y

ZEN 0349



D:9
L:62
P:29,64
E:10
IP:12,5
C:46,5
CW

CHITAHI:HONDA CIVIC/
NISSAN 120Y

ZEN 0351



D:9
L:62
P:29,64
E:10
IP:12,5
C:46,5
CW

HITACHI:S10 IMPORTADA
NISSAN

ZEN 0376



D:9
L:69
P:33
E:12
IP:14
C:60
CW

HITACHI:ISUZU KB10 D
NISSAN/MF 210-4

ZEN 0382



D:8
L:62
P:28
E:10
IP:12,5
C:46,5
CW

HITACHI: DATSUN
VANETTE/NISSAN

ZEN 0429



D:9
L:76,5
P:30
E:10
IP:12,51
C:46,5
CW

HITACHI:NISSAN FORK
LIFT


ZEN 0448



D:9
L:69
P:36
E:12
IP:14
C:60
CW

HITACHI:NISSAN CEDRIC/
PATROL/TERRANO II 2,7TD

ZEN 0499



D:8
L:28
P:60
E:10
IP:12,51
C:46,5
CW

HITACHI:BLUEBIRD 1,6-1,8
TURBO/Z20-Z22

ZEN 0517



D:8
L:82
P:28
E:10
IP:12,5
C:46,5
CCW

HITACHI:NISSAN SENTRA/
SUBARU JUSTY

ZEN 0536



D:9
L:39,5
P:30,0
E:6
IP:12,5
C:46,5
CCW

HITACHI:S108-116/61

ZEN 0539



D:10
L:69
P:39,5
E:12
IP:14
C:60
CW

HITACHI:NISSAN ED30

ZEN 0554



D:9
L:65
P:29,5
E:10
IP:12,5
C:46,5
CW

HITACHI:NISSAN V16
310/CHERRY AUTOM.

ZEN 0580



D:11
L:69
P:40,5
E:12
IP:14
C:60
CW

HITACHI:NISSAN /DATSUN
SD33

ZEN 0644



D:11
L:62
P:34,8
E:10
IP:12,5
C:46,5
CW

HITACHI:BOBCAT/NISSAN
FORK LIFTS/YANMAR

ZEN 0687



D:9
L:78
P:29,64
E:5
IP:12,5
C:46,5
CW

HITACHI:PICK UP/VG30
TERRANO 3,0

ZEN 0691



D:15
L:62
P:44,5
E:10
IP:12,5
C:54,5
CW

HITACHI:YANMAR

ZEN 0737



D:9
L:87
P:29,6
DC:41
C:53,2
CW

HITACHI:COMBO DIESEL/
REPARACION ZEN 1200

ZEN 0785



D:15
L:69
P:44,5
E:12
IP:14
C:60
CW

HITACHI:TRACTORS

ZEN 0790



D:9
L:87
P:36
DC:41
C:53,2
CW

HITACHI:NISSAN

ZEN 0791



D:8
L:87
P:28
DC:41
C:53,2
CW

HITACHI:NISSAN PRIMERA
PIÑON ZEN 9528



**IMPORTADORA
ISIS**

**Importación, Exportación
y Comercialización de Repuestos
de Vehículos**
Ignacio Carrera Pinto #1161, Rancagua.
Fono: 72-2-583570
ventas@importadoraisis.cl



ZEN 0792



D:9
L:87
P:33
DC:41
C:53,2
CW

HITACHI:THERMO KING/ISUZU
REPARACION ZEN 1200

ZEN 0793



D:8
L:94
P:28
DC:41
C:53,2
CCW

HITACHI:NISSAN SENTRA/
REPARACION ZEN 1207

ZEN 0828



D:9
L:66,0
P:29,64
E:5
IP:12,5
C:46,5
CW

HITACHI:SENTRA 4 CIL 2,0
1991-1994

ZEN 0832



D:9
L:77,0
P:29,64
E:10
IP:12,5
C:46,5
CW

HITACHI:ROVER 213/
HONDA CIVIC

ZEN 0844



D:9
L:87
P:25,9
DC:41
C:53,2
CW

HITACHI:VW LTTD/VOLVO
PIÑON ZEN 9566

ZEN 0901



D:11
L:77
P:40,50
E:12
IP:16
C:60
CW

HITACHI:NISSAN ED33-FD6
FORD LIFTS

ZEN 1016



D:8
L:75
P:28
E:10
IP:12,5
C:46,5
CCW

HITACHI:NEW HOLLAND

ZEN 1017



D:10
L:75
P:32,18
E:10
IP:12,5
C:46,5
CCW

HITACHI:AUDI A3 2002

ZEN 1020



D:8
L:38,5
P:28
E:10
IP:12,51
C:46,5
CW

HITACHI:NISSAN 200SX-
SENTRA

ZEN 1021



D:8
L:48,5
P:28
E:10
IP:12,5
C:46,5
CW

HITACHI:NISSAN /
DATSUN

ZEN 1532



D:8
L:61,5
P:28
E:10
IP:12,51
C:46,5
CCW

HITACHI:NISSAN V16

ZEN 1556



D:11
L:38,5
P:34,80
E:10
IP:12,51
C:46,5
CW

HITACHI:CASE CS27B/31B
36B/OPEL CORSA-ASTRA

ZEN 1557



D:13
L:38,5
P:33,30
E:10
IP:12,51
C:46,5
CW

HITACHI:OPEL ASTRA G1
7L TD 1998

ZEN 1608



D:9
L:92
P:35
DC:41
C:64,4
CW

HITACHI:SILVERADO /
PIÑON ZEN 13224

ZEN 1725



D:8
L:61,5
P:28
E:10
IP:12,0
C:46,5
CCW

HITACHI:MOTORES
ESTACIONARIOS

ZEN 1744



D:11
L:62
P:39,67
E:5
IP:12,51
C:46,6
CW

HITACHI:TRACTOR

ZEN 1762



D:10
L:44
P:27,94
E:10
IP:12,5
C:46,5
CW

HITACHI

ZEN 1779



D:10
L:38,6
P:27,94
E:10
IP:12,5
C:46,5
CW

HITACHI:FIAT BRAVO /
PALIO / PUNTO / SIENA

ZEN 1780



D:10
L:95,3
P:39,15
DC:41
C:53,2
CW


HITACHI:NISSAN NAVARA

ZEN 1858




D:9
L:100
P:36
CW

HITACHI:ISUZU NKR, NPR
22402500 (S25120A)




ZEN 1860



D:9
L:87
P:29,6
DC:41
IP:
C:53,2
CCW

HITACHI:YANMAR MARINE

ZEN 1861



D:9
L:95,3
P:33
DC:41
IP:
C:53,2

HITACHI:ISUZU

ZEN 1862



D:9
L:95,3
P:36

CW

HITACHI: TERRANO 2.7 Tdi
213095007-213015005

ZEN 1865



D:11
L:103,3
P:40,5

CCW

HITACHI:ISUZU NKR66
S25168A-S25515A


ZEN 1883



D:9
L:100
P:36
DC:41
IP:
C:53,2
CW

HITACHI:GRUA HORQUILLA
CLARK

ZEN 1866



D:9
L:95,3
P:33
DC:41
IP:
C:53,2

HITACHI:ISUZU

ZEN 1867



D:9
L:95,3
P:36

CW

HITACHI: TERRANO 2.7 Tdi
213095007-213015005

ZEN 1868




D:11
L:103,3
P:40,5

CCW

HITACHI:ISUZU NKR66
S25168A-S25515A


ZEN 1869



D:9
L:87
P:29,6
DC:41
IP:
C:53,2
CCW

HITACHI:YANMAR MARINE


ZEN 1870



D:9
L:95,3
P:33
DC:41
IP:
C:53,2

HITACHI:ISUZU

ZEN 1871




D:9
L:95,3
P:36

CW

HITACHI: TERRANO 2.7 Tdi
213095007-213015005

ZEN 1872




D:11
L:103,3
P:40,5

CCW

HITACHI:ISUZU NKR66
S25168A-S25515A


ZEN 1873



D:9
L:87
P:29,6
DC:41
IP:
C:53,2
CCW

HITACHI:YANMAR MARINE


ZEN 1874



D:9
L:95,3
P:33
DC:41
IP:
C:53,2

HITACHI:ISUZU

ZEN 1875




D:9
L:95,3
P:36

CW

HITACHI: TERRANO 2.7 Tdi
213095007-213015005

ZEN 1876




D:11
L:103,3
P:40,5

CCW

HITACHI:ISUZU NKR66
S25168A-S25515A


ZEN 1877



D:9
L:87
P:29,6
DC:41
IP:
C:53,2
CCW

HITACHI:YANMAR MARINE


ZEN 1878



D:9
L:95,3
P:33
DC:41
IP:
C:53,2

HITACHI:ISUZU

ZEN 1879




D:9
L:95,3
P:36

CW

HITACHI: TERRANO 2.7 Tdi
213095007-213015005

ZEN 1880



D:11
L:103,3
P:40,5

CCW

HITACHI:ISUZU NKR66
S25168A-S25515A